

EST GAL

Turnkey Hot Dip Galvanizing Plant
Design | Productions | Assembly

Dross Grap / Zinc Pump



Dross Grab

- It is used for the cleaning of zinc-iron components (Dross) formed in the galvanization furnace during the production

Zinc Pump

- They are used in the process of zinc discharge in case of emergency.

- The dimensions of design and manufacturing vary according to the dimensions of the galvanizing pot.

